

Appendix A: Photos of project area




Photo 1: 24/02/2026 – *General damage across sea wall*




Photo 2: 24/02/2026 – *General damage across sea wall*




Photo 3: 24/02/2026 – *General damage across sea wall*



Photo 4: 24/02/2026 – *General damage across sea wall*




Photo 5: 24/02/2026 – *General damage across sea wall*




Photo 6: 24/02/2026 – *Displacement of the outer limestone masonry blocks*



Photo 7: 24/02/2026 – Displacement of the outer limestone masonry blocks and the failed dowels



Photo 8: 24/02/2026 – Severely damaged lintels spanning over the canal



Photo 9: 24/02/2026 – Severely damaged lintels spanning over the canal



Photo 10: 24/02/2026 – *Displacement of the outer limestone masonry blocks and the failed dowels*



Photo 11: 24/02/2026 – *Bearing failure of the dowels*



Photo 12: 24/02/2026 – *Bearing failure of the dowels*



Photo 13: 24/02/2026 – *Bearing failure of the dowels and subsequent contact interface*



Photo 14: 24/02/2026 – *Underlying sand and/or fill material washed out resulting in the formation of voids*




Photo 15: 24/02/2026 – *Settlement of the adjacent stone paving*